

You may verify this report online at www.checkedandvetted.com/GLBBuildersLimited/
or by phoning Checked and Vetted on 0191 65-111-65

GLB Builders Limited

Checked and Vetted Membership

Member Since : 22-Mar-2012

Member Number : 148477

Contact Information

Name : Mr Graham Beston

Address : Hebburn
Tyne and Wear NE31 1RS

Telephone :

Mobile : 07870690831

Web : www.facebook.com/GLB-Builders-172751479470325/

About this Tradesman

Limited Company : yes, 09631315

Vat Registered : No

Public Liability Cover : Current-Verified till 16 May 2026

Cover Amount : 1,000,000

Insured By : AVIVA

Accreditations

Checked and Vetted No. 148477

Federation of Small Businesses No. 30109896

No. 4847

Recent Customer Feedback

I have a wheelchair and the brick ramp up to my front door was dipping so it needed a good levelling. 10 / 10

Graham has done an amazing piece of work on my dipping brick ramp. His work from my experience is second to none, he went above and beyond initial discussion and really helped me all he could. The ramp looks better than when new, absolutely first class, such craftsmanship. I am thrilled and can thoroughly recommend and I am hard to please so this is praise indeed.

Customer in Washington, 11-Jun-2026

Removal of old radiators and refitting 6 x designer radiators including associated plumbing and plastering work. 10 / 10

GLB offers a great service and can be trusted to carry out any work with professionalism. Graham's standards are extremely high and we have engaged GLB to carry out work on our property several times over the last few years. I have no hesitation in recommending GLB.

Customer in Hebburn, 13-Mar-2026

Moving position and installing new radiator 10 / 10

As always a great job, work is always top class and very thorough.

Customer in Sunderland, 09-Mar-2026

Replace bathroom taps. 10 / 10

Carried out on time, took the time to show us there were no leaks before bath panel was refitted and left no mess.

Customer in Gateshead, 14-Jan-2026

Located cause of persistent sewage smell in bathroom due to dislodged soil pipe which was leaking sewage behind fitted bath. 10 / 10

Graham was already due to do some work at my house, but I asked him to try to find the source of a persistent bad smell in bathroom as had had 5 visits from well known plumbing company who had not sorted it out! Graham quickly found the problem which was a dislodged soil pipe leaking sewage behind and under the bath each time toilet flushed! The sewage had to be removed and he fitted new soil pipes and new pan connector.

This was a difficult awkward job because of the fitted bath. He did a great job and as always great attention to detail + a useful sense of humour.

Customer in Sunderland, 04-Dec-2025